

# ALERT SERVICE BULLETIN

FROM PRODUCT SUPPORT DEPARTMENT, GOVERNMENT AIRCRAFT FACTORIES.

NOMAD ALERT SERVICE BULLETIN N22-27-5

1. ALL NOMAD OPERATORS - RUDDER CONTROL SYSTEM
2. AS A RESULT OF INCIDENT ON ONE AIRCRAFT INVOLVING RUDDER CABLE CIRCUIT NO REPEAT NO TRAINING IS TO BE CARRIED OUT IN ASSYMETRIC FLIGHT UNTIL FURTHER NOTICE
3. NOTE THAT AIRCRAFT MUST NOT BE TOWED WITH CONTROL LOCK INSTALLED
4. REMEDIAL SERVICE BULLETIN TO FOLLOW.

10th December, 1976

S/B N22-27-5