

Service Bulletin

Subject:

Flush Fuel Filler Caps.

Applicability:

GA8 aircraft S/N GA8-00-004 to GA8-02-012, GA8-02-015 and GA8-02-016.

Background:

The affected aircraft were manufactured using a steel filler cap assembly. At the owners discretion this may be replaced by a flush filler cap as used on later aircraft.

Instructions:

The new fuel filler cap must be installed in accordance with Gippsland Aeronautics drawing GA-0341 sheets 1 through 3 all at issue 1

Drawings and parts may be purchased from Gippsland Aeronautics.

Weight and Balance:

Negligible effect on weight and balance.

Approval:

This Service Bulletin has been approved pursuant to Regulation 35 of CAR1988.

Documentation:

Update aircraft log book to reflect incorporation of this Service Bulletin.

Compliance Notice:

Complete the Document Compliance Notice and return to Gippsland Aeronautics by fax/mail.

DOCUMENT COMPLIANCE NOTICE



Document: Service Bulletin SB-GA8-2004-13

Aircraft Serial Number: GA8-_____

I/we have incorporated Service Bulletin SB-GA8-2004-13 for the above aircraft.

Signed

Print name_____

Please post or fax this compliance notice to:

Gippsland Aeronautics
Attn: Technical Services
P.O. Box 881
Morwell Victoria 3840
Australia
Fax.: +61 03 5172 1201