

Service Bulletin

Subject:

Eligibility of GA8 aircraft for Papua New Guinea certification.

Applicability:

All GA8 aircraft certified in Papua New Guinea.

Amendments:

Nil – Initial Issue.

Background:

Certification in the Papua New Guinea requires compliance with PNG Civil Aviation Rules Part 21 and Part 26.

Compliance:

This Service Bulletin must be incorporated prior to the issue of a PNG Certificate of Airworthiness.

Weight and Balance:

Negligible effect on weight and balance.

Approval:

The technical aspects of this Service Bulletin have been approved under a CASA Authorisation.

Parts:

Item	P/N	Description	Qty
1	GA8-113024-21 ¹	Emergency Exit Placard	2
2	GA8-113024-23	Exit Placard	2

Parts Availability:

New parts can be obtained directly from Gippsland Aeronautics.

Tel.: +61 03 5172 1200

Fax.: +61 03 5172 1201

Email: spares@gippsaero.com

Instructions:

Placard Installation

1. Install item 1 placard on the outside of the front doors as indicated in Figure 1.
2. Install item 2 placard on the inside and outside of the rear door as indicated in Figures 2 and 3.




Figure 1 – External Placard on Front Doors



Figure 2 – External Placard on Rear Door



Figure 3 – Internal Placard on Rear Door

Documentation:

Update aircraft log book to reflect incorporation of this Service Bulletin.

Compliance Notice:

Complete the Document Compliance Notice and return to Gippsland Aeronautics by fax/mail.

DOCUMENT COMPLIANCE NOTICE



Document: Service Bulletin SB-GA8-2005-27

Aircraft Serial Number: GA8-_____

I/we have incorporated Service Bulletin SB-GA8-2005-27 for the above aircraft.

Signed

Print Name

Please post or fax this compliance notice to:

Gippsland Aeronautics
Attn: Technical Services
P.O. Box 881
Morwell Victoria 3840
Australia
Fax.: +61 03 5172 1201